


Index No. J 15

CASS COUNTY LAND CORNER RECORD

T. 140 R. 27 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
N14 15 Corner common to sections 10, 15



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1873  
Original monument Post

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

Bearing Trees

Species	<u>W. Birch</u>	<u>Balsam</u>	_____	_____
Diameter	<u>10"</u>	<u>6"</u>	_____	_____
Bearing	<u>S74E</u>	<u>N72-40E</u>	_____	_____
Distance	<u>17LKS</u>	<u>17LKS.</u>	_____	_____

Original Bearing Trees Found

Species	_____	_____	_____	_____
Diameter	_____	_____	_____	_____
Bearing	_____	_____	_____	_____
Distance	_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1937 By CCC  
Location filed Washburn Lake - Bk#6 p. 53  
Monument at 2604' from E. 45' south of  
1 1/4" iron pipe

Evidence of Subsequent Corner Restoration

Year of search \_\_\_\_\_ By \_\_\_\_\_

Bearing Trees, Reference Objects

Species	_____	_____	_____	_____
Diameter	_____	_____	_____	_____
Bearing	_____	_____	_____	_____
Distance	_____	_____	_____	_____

Bearing Trees, Reference Objects

_____	_____	_____	_____	_____
_____	_____	_____	_____	_____
_____	_____	_____	_____	_____
_____	_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_

Remonumentation certificate prepared \_\_\_\_\_

By \_\_\_\_\_

Filed at \_\_\_\_\_

Date \_\_\_\_\_