


Index No. 517

CASS COUNTY LAND CORNER RECORD

T. 140 R. 27 M. 5TH Coordinates: X _____ Y _____
NE 15 Corner common to sections 10, 11, 14, 15



EXISTING SURVEYS

Original Government Survey

Year surveyed 1873
Original monument POST

Original Evidence Found

Year of search _____ By _____
Monument found _____

		Bearing Trees	
Species	<u>ASH</u>	<u>ASH</u>	<u>W. BIRCH</u>
Diameter	<u>6"</u>	<u>6"</u>	<u>4"</u>
Bearing	<u>N70-20E</u>	<u>S70-15E</u>	<u>S80W</u>
Distance	<u>20 LKS</u>	<u>15 LKS</u>	<u>32 LKS</u>

Original Bearing Trees Found

Species	_____
Diameter	_____
Bearing	_____
Distance	_____

○ = Corner

Subsequent Corner Restoration

Year surveyed 1906 By JOHN CURO
Location filed County Survey Record Book A" P 309-312
Monument Find ORIG Post & ORIG BITS - DOWN REPLACE POST
WITH 4x4x36" Post IN 1911 Set 2 1/2 x 18" I.P. IN
CONCRETE

Evidence of Subsequent Corner Restoration

Year of search 1937 By CCC
Washburn Lake - BK # 6 P. 52
at 5327' from E - Find 2" I.P. w/ cap alongside
4" sq post
1911 - Harry Todd - microfilm - roll 115 BK 93 P. 8
Find corner set by Curo

Bearing Trees, Reference Objects

Species	<u>ASH</u>	<u>ASH</u>	<u>W. BIRCH</u>	<u>TAM</u>
Diameter	<u>6"</u>	<u>6"</u>	<u>4"</u>	<u>12"</u>
Bearing	<u>N70-20E</u>	<u>S70-15E</u>	<u>S80W</u>	<u>N40W</u>
Distance	<u>13.2'</u>	<u>9.9'</u>	<u>13.2'</u>	<u>21.1'</u>

Bearing Trees, Reference Objects

Species	_____
Diameter	_____
Bearing	_____
Distance	_____

10" Poplar N86-53E 130.15', 8" Poplar S36-07E 113.75'
1906 fics

Subsequent Corner Restoration 5 17

Year surveyed 1910 By A. W. Markster
Location filed Microfilm - roll 115 BK 91 P. 5
Monument Find corner

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Mar 1999 CC Land Dept - A. R. John
Got metal detector reading in road

P-Pole on E side of road
20" R. line on W. side of road

Remonumentation certificate prepared _____

By _____

Filed at _____

Date _____