


Index No. J 19

CASS COUNTY LAND CORNER RECORD

T. 140 R. 27 M. 5TH Coordinates: X 11,14 Y 4,71
N. 14 14 Corner common to sections 11,14 W.C. 4,71 CH. EAST
W.C. 5.90 CH. WEST



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1873
Original monument POST'S FOR W.C.'S

Original Evidence Found

Year of search _____ By _____
Monument found _____

Species	Bearing	Tree	Distance
<u>POPLAR</u>	<u>POPLAR</u>	<u>POPLAR</u>	<u>POPLAR</u>
<u>4"</u>	<u>5"</u>	<u>4"</u>	<u>4"</u>
<u>N87W</u>	<u>N53E</u>	<u>S47W</u>	<u>N89W</u>
<u>52 LKS</u>	<u>39 LKS</u>	<u>23 LKS</u>	<u>33 LKS</u>
<u>4.71 CH. EAST</u>		<u>5.90 CH. WEST</u>	

Original Bearing Trees Found

Species	Diameter	Bearing	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1937 By CCC
Location filed Washburn Lake - BK# 6 P. 51
Monument at 2640' from E - set approx cor.

Evidence of Subsequent Corner Restoration

Year of search 1910 E 116 By CUVO
Microfilm - Roll 105 BK 48 P. 57
for E 116 set 3 1/2 x 3 1/2 x 30" oak post

Bearing Trees, Reference Objects

Species	Diameter	Bearing	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Bearing Trees, Reference Objects

Species	Diameter	Bearing	Distance
<u>J. Pine</u>	<u>5"</u>	<u>N87-45W</u>	<u>150.6'</u>
<u>Poplar</u>	<u>8"</u>	<u>N45-08E</u>	<u>109.75'</u>

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Remonumentation certificate prepared _____
Filed at _____

By _____
Date _____