


Index No. J 20

CASS COUNTY LAND CORNER RECORD



T. 140 R. 27 M. 5th Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
E 116 Corner common to sections 11 and 14

EXISTING SURVEYS

Original Government Survey

Original Evidence Found

Year surveyed \_\_\_\_\_  
Original monument \_\_\_\_\_

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

Bearing Trees

Species	_____	_____	_____	_____
Diameter	_____	_____	_____	_____
Bearing	_____	_____	_____	_____
Distance	_____	_____	_____	_____

Original Bearing Trees Found

Species	_____	_____	_____	_____
Diameter	_____	_____	_____	_____
Bearing	_____	_____	_____	_____
Distance	_____	_____	_____	_____

Subsequent Corner Restoration

Evidence of Subsequent Corner Restoration

Year surveyed 1998 By CCSO  
Location filed CCSO  
Monument 1.5" OD IP up 1.5' near 2 PI.  
Co. Rd. No. 55.

Year of search \_\_\_\_\_ By \_\_\_\_\_

Bearing Trees, Reference Objects

Species	<u>Aspen</u>	<u>Tr. Birch</u>	<u>W. Oak</u>	<u>W. Oak</u>
Diameter	<u>5"</u>	<u>6"</u>	<u>5"</u>	<u>7"</u>
Bearing	<u>N80°W</u>	<u>N17°W</u>	<u>N44°E</u>	<u>N70°E</u>
Distance	<u>27.38*</u>	<u>30.27*</u>	<u>43.70*</u>	<u>48.91*</u>

Bearing Trees, Reference Objects

\* Distance to double head nail

Subsequent Corner Restoration

Evidence of Subsequent Corner Restoration Found

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

Year of search \_\_\_\_\_ By \_\_\_\_\_