


Index No. J 21

CASS COUNTY LAND CORNER RECORD

T. 140 R. 27 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
NE 14 Corner common to sections 11, 12, 13, 14



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1873  
Original monument POST

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

Bearing Traces

Species	<u>W. OAK</u>	<u>ASPEN</u>	<u>ASPEN</u>	<u>W. BIRCH</u>
Diameter	<u>6"</u>	<u>4"</u>	<u>4"</u>	<u>8"</u>
Bearing	<u>S 20-30E</u>	<u>S 17-40W</u>	<u>N 36-20W</u>	<u>N 47-45E</u>
Distance	<u>35 LKS</u>	<u>41 LKS</u>	<u>73 LKS</u>	<u>6 LKS</u>

Original Bearing Trees Found

Species	_____	_____	_____	_____
Diameter	_____	_____	_____	_____
Bearing	_____	_____	_____	_____
Distance	_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1909 By JOHN CUKO  
Location filed COUNTY SURVEY RECORD BOOK "A" P 308-312  
Monument SET STAKE FROM ORIG. BITS: 6" W. OAK S 20-30E  
23.1', 8" W. BIRCH N 47-45E 4.0'  
IN 1911 SET 2 1/2" x 48" IRON IN CONCRETE

Evidence of Subsequent Corner Restoration

Year of search 1937 By CCC  
Washington Lake - BK # 6 P. 50  
Start west from intersection of roads

Bearing Trees, Reference Objects

Species OAK  
Diameter \_\_\_\_\_  
Bearing S 58-41E  
Distance 10.54'

Bearing Trees, Reference Objects

\_\_\_\_\_

J-21

Subsequent Corner Restoration

Year surveyed 1917 By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument CO. DITCH SURVEY BK 28 BOX 2  
OF A DITCH SURVEY BOOBS, PG 82

Evidence of Subsequent Corner Restoration Found

Year of search 1998 By CCSO  
Fd. in place RLS capped I.P. #17008  
in E of Driveway near PI of Co. Rd.  
No. 55 E. Add witnesses as follows:  
7" Maple, S 60° E, 82.73' \*  
9" W. Oak, S 14° E, 99.26' \*  
10" W. Oak, S 49° W, 128.47' \*  
30" R. Pine, N 23° W, 137.10' \*  
\* Distance to double head nail

Remonumentation certificate prepared \_\_\_\_\_

By \_\_\_\_\_

Filed at \_\_\_\_\_

Date \_\_\_\_\_