


T. 140 R. 27 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
NE 17 Corner common to sections 8, 9, 16, 17



EXISTING SURVEYS

Original Government Survey

Year surveyed 1873  
 Original monument Post

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
 Monument found \_\_\_\_\_

Species	Bearing Trees			
	TAM.	TAM.	TAM.	TAM.
Diameter	18"	12"	8"	10"
Bearing	579E	N75-30E	574W	N30-40W
Distance	37 LKS.	158 LKS	114 LKS	104 LKS

Original Bearing Trees Found

Species	Diameter	Bearing	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1948 By HAROLD Curo  
 Location filed COUNTY BOOK D P 336  
 Monument PULL WOOD STAKE SET PREVIOUSLY FROM ORIG.  
U.S. B.T.S SET 2X30" I.P.

Evidence of Subsequent Corner Restoration.

Year of search 1938 By CCC  
Washburn Lake - BK#6 P.57  
9t 5280' from E Set approx Sec. Cor.  
BK#6 P.60 continue w. 112' find true Cor.  
7' N. find 3' long Sapost w/ scribing and B.T.S.  
14" Aspen N53'2w 16', 14" Aspen S5w 39' w/ scribing  
BK#6 P.77 - started South from Corner  
 Bearing Trees, Reference Objects

Bearing Trees, Reference Objects

Species	Poplar	Poplar	Poplar	BIRCH
	Diameter	9"	8"	9"
Bearing	N10E	543E	550W	N40W
Distance	6.20'	31.00'	50.90' or 29.50'	21.70'

Subsequent Corner Restoration 29

Year surveyed 1940 By CCC  
 Location filed Washburn Lake - BK#20  
 Monument Find wood post & 2 B.T.S corner is 200'  
east & 374' South of Road  
1918 Co DITCH SURVEY BK 10 BOX 2 OF  
Co DITCH SURVEY BOOKS, PG 6

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Certificate - Bert Evenden - DNR - 1985  
Find 1 3/8" I.P. and H. Curo 1948 ties  
12" Poplar snag 543E 30.8' Blazed  
14" Birch stump N60W 22.7' } 1948 Curo  
Dead 14" Poplar N7E 8.5' Blazed } ties  
6" Ash N46E 26.67'  
11" Ash N40W 23.68'  
8" Ash 550W 33.43'  
547E 38.39'  
Doc. # 280019  
admitted 1st time:  
13" Elm - DNR disc ('85) S 53E 38.39'