


Index No. L 25

CASS COUNTY LAND CORNER RECORD

T. 140 R. 27 M. 5TH Coordinates: X _____ Y _____
E/4 13 Corner common to sections 13 AND 18-140-26



EXISTING SURVEYS

Original Government Survey

Year surveyed 1864
Original monument Post

Original Evidence Found

Year of search _____ By _____
Monument found _____

Bearing Trees
Species CEDAR W. BIRCH
Diameter 5" 8"
Bearing N 49 E N 86 W
Distance 25 LKS 14 LKS

Original Bearing Trees Found

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed 1937 By CCC
Location filed Washburn Lake - BK# 6 P. 28
Monument at 2640 from S - Sect Approx Cor.

Evidence of Subsequent Corner Restoration

Year of search 7/2001 By CCSO
Found CIM, 1.5' under water, 15'±
from shore of pond.

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Bearing Trees, Reference Objects

N. PINE maple Cedar
18" 6" 12"
N 64° W S 62° W S 83° E
77.45' 26.52' 28.49'
dbl. hd. nail dbl. hd. nail nail + disk

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Remonumentation certificate prepared _____

By _____

Filed at _____

Date _____