


Index No. N 23

CASS COUNTY LAND CORNER RECORD

T. 140 R. 27 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
N114 24 Corner common to sections 13, 24



EXISTING SURVEYS

**Original Government Survey**  
 Year surveyed 1873  
 Original monument Post

**Bearing Trees**

Species	<u>TAM.</u>	<u>TAM</u>
Diameter	<u>5"</u>	<u>5"</u>
Bearing	<u>N10E</u>	<u>S30E</u>
Distance	<u>8 LKS</u>	<u>8 LKS</u>

**Original Evidence Found**  
 Year of search \_\_\_\_\_ By \_\_\_\_\_  
 Monument found \_\_\_\_\_

**Original Bearing Trees Found**

Species	_____	_____
Diameter	_____	_____
Bearing	_____	_____
Distance	_____	_____

**Subsequent Corner Restoration**  
 Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
 Location filed \_\_\_\_\_  
 Monument \_\_\_\_\_

**Evidence of Subsequent Corner Restoration**  
 Year of search Feb 2003 By CCSO  
Set alum. cap telescope, up 0.5', in  
spruce and tamarack swamp.

**Bearing Trees, Reference Objects**

Species	_____	_____
Diameter	_____	_____
Bearing	_____	_____
Distance	_____	_____

**Bearing Trees, Reference Objects**

<u>Blk. Spruce</u>	<u>Blk. Spruce</u>	<u>Tamarack</u>
<u>8"</u>	<u>6"</u>	<u>8"</u>
<u>N38°W</u>	<u>N2°E</u>	<u>S25°E</u>
<u>36.04'</u>	<u>31.87'</u>	<u>16.27'</u>
<u>dbl hd nail</u>	<u>dbl hd nail</u>	<u>dbl hd nail</u>

**Subsequent Corner Restoration**  
 Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
 Location filed \_\_\_\_\_  
 Monument \_\_\_\_\_

**Evidence of Subsequent Corner Restoration Found**  
 Year of search \_\_\_\_\_ By \_\_\_\_\_