


T. 140 R. 27 M. 5TH Coordinates: X _____ Y _____
NE 28 Corner common to sections 21, 22, 27, 28



EXISTING SURVEYS

Original Government Survey

Year surveyed 1873
Original monument Post

Original Evidence Found

Year of search _____ By _____
Monument found _____

	Bearing Trees			
Species	<u>W. PINE</u>	<u>W. PINE</u>	<u>N. PINE</u>	<u>POPLAR</u>
Diameter	<u>14"</u>	<u>22"</u>	<u>24"</u>	<u>10"</u>
Bearing	<u>S 71-30 E</u>	<u>S 75-40 W</u>	<u>N 56-30 W</u>	<u>56 E</u>
Distance	<u>98 LKS</u>	<u>86 LKS</u>	<u>131 LKS</u>	<u>169 LKS</u>

Original Bearing Trees Found

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

O = Corner

Subsequent Corner Restoration

Year surveyed 1938 By CCC
Location filed Washburn Lake - BK # 6. P. 70
Monument at 5200' from east - set approx cor.
BK # 9 P. 14 - start N. from approx cor.

Evidence of Subsequent Corner Restoration

Year of search 5/24/91 By David Landecker
Set 11' aluminum rod with aluminum cap.

Bearing Trees, Reference Objects

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Bearing Trees, Reference Objects

<u>Ash (Twin)</u>	<u>Maple</u>	<u>Birch</u>
<u>8"</u>	<u>12"</u>	<u>8"</u>
<u>N 40 W</u>	<u>S 18 W</u>	<u>S 75 W</u>
<u>68.00'</u>	<u>40.95'</u>	<u>65.57'</u>

R - 13

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
1991 Cert. Filed by David Landecker
Doc. # 329221