


T. 140 R. 27 M. 5TH Coordinates: X _____ Y _____
NE 29 Corner common to sections 20, 21, 28, 29



EXISTING SURVEYS

Original Government Survey
 Year surveyed 1873
 Original monument Post

Original Evidence Found
 Year of search _____ By _____
 Monument found _____

Species	Bearing	Trces	
<u>SPRUCE</u>	<u>BIRCH</u>	<u>BIRCH</u>	<u>TAM</u>
Diameter <u>7"</u>	<u>9"</u>	<u>6"</u>	<u>7"</u>
Bearing <u>S62-70W</u>	<u>N70W</u>	<u>N4-45E</u>	<u>S40-20E</u>
Distance <u>40 LKS</u>	<u>67 LKS</u>	<u>33 LKS</u>	<u>115 LKS</u>

Original Bearing Trees Found
 Species _____
 Diameter _____
 Bearing _____
 Distance _____

Subsequent Corner Restoration
 Year surveyed 1938 By CCC
 Location filed Washburn Lake - BK# 6 P. 72
 Monument at 5280 from east - set app. cor.
Found 3" post squared on 2 sides 115' S of
line
BK# 9 R1 Start west from Cor 115' S.

Evidence of Subsequent Corner Restoration
 Year of search 1991 By David Landecker
Set 2" square tubular monument 36" long
with aluminum cap, up 10".

Bearing Trees, Reference Objects
 Species _____
 Diameter _____
 Bearing _____
 Distance _____

Maple	Burr Oak	Birch
Diameter <u>10"</u>	<u>8"</u>	<u>10"</u>
Bearing <u>N32W</u>	<u>N36E</u>	<u>S50W</u>
Distance <u>60.88'</u>	<u>26.03'</u>	<u>33.79'</u>

Subsequent Corner Restoration
 Year surveyed _____ By _____
 Location filed _____
 Monument _____

Evidence of Subsequent Corner Restoration Found
 Year of search _____ By _____
1991 Cert. Filed by David Landecker
Doc. # 329219.
March 2005 Found by Amy Rand
(Cass County Land Dept) Excellent Condition

R-9