Index No. V3

CASS COUNTY LAND CORNER RECORD

T. 140 R. 27 M. 5TH Coordinates: X _____ Y _____

N1/4 31 Corner common to sections 30, 31



O = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1873

Original monument Post

Original Evidence Found

Year of search _____ By _____

Monument found _____

Bearing Trees

Species	TAM.	TAM.		
Diameter	4"	4"		
Bearing	S42-30E	N69-45W		
Distance	23 LKS	10 LKS		

Original Bearing Trees Found

Species				
Diameter				
Bearing				
Distance				

Subsequent Corner Restoration

Year surveyed 1938 By CCC

Location filed Washburn Lake - BK#9 P. 6

Monument at 25.27' from W 1½" IR. 31' N. of line BK#20 530' South of central post on road.

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

Bearing Trees, Reference Objects

Species				
Diameter				
Bearing				
Distance				

Bearing Trees, Reference Objects

Subsequent Corner Restoration

Year surveyed _____ By _____

Location filed _____

Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Remonumentation certificate prepared _____ By _____

Filed at _____ Date _____