Index No. G 17

CASS COUNTY LAND CORNER RECORD

T. 140 R. 28 M. 5TH Coordinates: X _____ Y _____

E1/4 10 Corner common to sections 10, 11



EXISTING SURVEYS

Original Government Survey

Year surveyed 1870

Original monument POST

Original Evidence Found

Year of search _____ By _____

Monument found _____

Bearing Trees

Species	POPLAR	BIRCH		
Diameter	6"	12"		
Bearing	S10E	S15W		
Distance	75 LKS	10 LKS.		

Original Bearing Trees Found

Species				
Diameter				
Bearing				
Distance				

Subsequent Corner Restoration

Year surveyed 1919 By BEN CLARK

Location filed COUNTY BOOK "C" P.199, 200

Monument FND OAK POST 3"X36" AND COUT B.T.: 12" W. BIRCH S15W 10LKS. SET 2X48" I.M.

Evidence of Subsequent Corner Restoration

Year of search 1941 By CCC

Washburn Lake - BK# 15 P.33

at 2640' from South - set approx 1/4 COR 2" cedar.

1965 - Co. Hwy Dept., Co. Rd # 54 Found Corner

Bearing Trees, Reference Objects

Species	MAPLE	OAK		
Diameter	8"	4"		
Bearing	N22W	S25E		
Distance	16.7'	15.6'		

Bearing Trees, Reference Objects

G-17

Subsequent Corner Restoration

Year surveyed APRIL 2000 By MN/DNR J. WALKER

Location filed

Monument CERT OF LOCATION DOC. # 430974

SET 3/4" x 24" REBAR IN FOUND 2" O.D. IRON PIPE

DNR RP 14" OAK N 55°W 17.02
DNR RP 12" OAK N 65°E 56.47
DNR RP 14" OAK S 60°E 41.53
SE COR. EASTER CABIN S 5°W 197.80

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Remonumentation certificate prepared _____ By _____

Filed at _____ Date _____