


Index No. G 9

CASS COUNTY LAND CORNER RECORD

T. 140 R. 28 M. 5TH Coordinates: X _____ Y _____
E114 B Corner common to sections 8, 9



EXISTING SURVEYS

Original Government Survey

Year surveyed 1870
Original monument POST

Original Evidence Found

Year of search _____ By _____
Monument found _____

Bearing Trees

Species MAPLE IRONWOOD _____
Diameter 7" 5" _____
Bearing NBSE S12W _____
Distance 34 LKS 27 LKS _____

Original Bearing Trees Found

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed 1941 By CCC
Location filed Washburn Lake - BK# 15 P. 45
Monument at 2640' from South - set approx cor
2" Aspen

Evidence of Subsequent Corner Restoration

Year of search Apr. 2003 By CCSO
Found 2" ODIP, up 2.7', on N. side
of ridge.

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

May 1915; B.F. Clark

Top rd order shows survey

Bearing Trees, Reference Objects

Maple tw A. Oak Maple
8" 8" 10"
N 74° W S 7° W S 57° E
24.96' 13.44' 32.84'

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Remonumentation certificate prepared _____

By _____

Filed at _____

Date _____