


T. 140 R. 28 M. 5TH Coordinates: X _____ Y _____
NE 24 Corner common to sections 13, 24 and 18, 19-140-27



EXISTING SURVEYS

Original Government Survey

Year surveyed 1863

Original monument Post

Bearing Trees			
Species	<u>CEGAR</u>	<u>TAM.</u>	<u>CEGAR</u>
Diameter	<u>10"</u>	<u>10"</u>	<u>8"</u>
Bearing	<u>N32E</u>	<u>S48E</u>	<u>S37W</u>
Distance	<u>6LKS</u>	<u>13LKS</u>	<u>17LKS</u>

Original Evidence Found

Year of search _____ By _____

Monument found _____

Original Bearing Trees Found

Species _____

Diameter _____

Bearing _____

Distance _____

○ = Corner

Subsequent Corner Restoration

Year surveyed 1938 By CCC

Location filed Washburn Lake - BK# 9, P. 7

Monument at 5280' from east - 4" spruce stump
for approx cor.

1941 - BK# 14 P. 16 at 5158' from South End iron
pipe

Evidence of Subsequent Corner Restoration

Year of search 1983 By Freeman - Harrington - Lamm
Survey Tech. - Land Commissioner -
Forester

End 2" i.p. up 2' new ties below

Bearing Trees, Reference Objects

Species _____

Diameter _____

Bearing _____

Distance _____

Bearing Trees, Reference Objects

<u>Cedar</u>	<u>Cedar</u>	<u>Cedar</u>
<u>4"</u>	<u>4"</u>	<u>10"</u>
<u>N67W</u>	<u>S16W</u>	<u>N82E</u>
<u>10.82'</u>	<u>8.70'</u>	<u>16.66'</u>

Subsequent Corner Restoration

Year surveyed _____ By _____

Location filed _____

Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search 2000 By CCSO

End impl. 2" ODIP up 2.0'. Located
in Cedar swamp.

REF. TIES:

<u>4" Cedar</u>	<u>S16°W</u>	<u>8.70'</u>
<u>4" Cedar</u>	<u>N67°W</u>	<u>10.82'</u>
<u>10" Bk. Spruce</u>	<u>N6°E</u>	<u>29.40'</u>
<u>10" Cedar</u>	<u>N82°E</u>	<u>16.66'</u>

* ref. to dbl. hd. nails