


Index No. N 6-7

CASS COUNTY LAND CORNER RECORD

T. 140 R. 28 M. 5TH Coordinates: X _____ Y _____
 MC# 63 Corner common to sections 17,20



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1870
 Original monument POST

Bearing Trees	
Species <u>N. Pine</u>	<u>W. Ash</u>
Diameter <u>4"</u>	<u>4"</u>
Bearing <u>55E</u>	<u>N70W</u>
Distance <u>38 LKS</u>	<u>7 LKS</u>

Original Evidence Found

Year of search _____ By _____
 Monument found _____

Original Bearing Trees Found

Species _____	_____
Diameter _____	_____
Bearing _____	_____
Distance _____	_____

Subsequent Corner Restoration

Year surveyed 1917 By E. B. West
 Location filed County Book "C" P. 70
 Monument FRD 2 1/2 x 4 8" I.M. W.C.M.C. 25.8'E OF MC.
1927? Greene? microf. film - roll 115 BK77
P. 142 I.M. wit post 25.8'E

Evidence of Subsequent Corner Restoration

Year of search 1911 By A. W. Maultsby
Microf. film - roll 105 BK 49 P. 42
End stump of N. Pine B.T.

Bearing Trees, Reference Objects

<u>N. Pine stump</u>	_____
<u>12"</u>	_____
<u>S-E</u>	_____
<u>beside old B.T.</u>	_____

Bearing Trees, Reference Objects

Species _____	_____
Diameter _____	_____
Bearing _____	_____
Distance _____	_____

Subsequent Corner Restoration

Year surveyed Nov 2002 By CCSO
 Location filed _____
 Monument MC 17:20 / 140:28
fd. 2 1/4" OPIL w/plumber cap, up 2.0',
on edge of bank, 23' ± from waters
edge.

16" N. Pine N 10° E 16.89' up 1.0' E. side
8" R. Oak S 45° E 16.84' up 1.0' S. side
Dist. to dbl bd nail

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Re monumentation certificate prepared _____ By _____
 Filed at _____ Date _____