


Index No. N 7

CASS COUNTY LAND CORNER RECORD

T. 140 R. 28 M. 574 Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
N<sup>1</sup>/<sub>4</sub> 20 Corner common to sections 17, 20



O = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1870  
Original monument Post

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

Bearing Trees  
Species BL. OAK Poplar  
Diameter 9" 4"  
Bearing N32E S25E  
Distance 90 LKs 22 LKs

Original Bearing Trees Found  
Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Subsequent Corner Restoration

Year surveyed Nov 2008 By CCSO  
Location filed \_\_\_\_\_  
Monument N<sup>1</sup>/<sub>4</sub> - Found 2<sup>1</sup>/<sub>4</sub> ODIP, flush, 14<sup>±</sup> N. of & driveway.

Evidence of Subsequent Corner Restoration

Year of search \_\_\_\_\_ By \_\_\_\_\_

\* - Dist. to dbl. head nail

Bearing Trees, Reference Objects  
Species Maple W. Pine R. Oak  
Diameter 6" 12" 12"  
Bearing N80<sup>o</sup>W N88<sup>o</sup>E S12<sup>o</sup>E  
Distance 18.08'\* 45.82'\* 33.21'\*  
up 1.0 N. side up 1.0 S. side up 1.0 W. side

Bearing Trees, Reference Objects

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_

Remonumentation certificate prepared \_\_\_\_\_

By \_\_\_\_\_

Filed at \_\_\_\_\_

Date \_\_\_\_\_