


Index No. P 25

CASS COUNTY LAND CORNER RECORD

T. 140 R. 28 M. 5th Coordinates: X _____ Y _____
E1/4 24 Corner common to sections 24 AND 19-140-27



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1863

Original monument post

Species	Bearing	Trees
<u>SPRUCE</u>	<u>W. BIRCH</u>	
<u>4"</u>	<u>5"</u>	
<u>N 86 E</u>	<u>N 73 W</u>	
<u>24 LKS</u>	<u>15 LKS.</u>	

Original Evidence Found

Year of search _____ By _____

Monument found _____

Original Bearing Trees Found

Species	Bearing	Distance
_____	_____	_____
_____	_____	_____
_____	_____	_____
_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1939 By CCC

Location filed Washburn Lake - BK# 13 P. 5

Monument at 2640' from South - set approx 1/4 cor
3" sq Jack pine

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

Bearing Trees, Reference Objects

Species	Bearing	Distance
_____	_____	_____
_____	_____	_____
_____	_____	_____
_____	_____	_____

Bearing Trees, Reference Objects

Species	Bearing	Distance
_____	_____	_____
_____	_____	_____
_____	_____	_____
_____	_____	_____

Subsequent Corner Restoration

Year surveyed _____ By _____

Location filed _____

Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
