


Index No. Q-R 5

CASS COUNTY LAND CORNER RECORD

T. 140 R. 28 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
M.C.# 46 Corner common to sections 19, 20



EXISTING SURVEYS

**Original Government Survey**  
 Year surveyed 1870  
 Original monument POST

**Bearing Trees**

Species	<u>TAM.</u>	<u>DRY TAM.</u>
Diameter	<u>7"</u>	<u>9"</u>
Bearing	<u>N29E</u>	<u>N37W</u>
Distance	<u>28 LKS</u>	<u>17 LKS.</u>

**Original Evidence Found**  
 Year of search \_\_\_\_\_ By \_\_\_\_\_  
 Monument found \_\_\_\_\_

**Original Bearing Trees Found**

Species	_____	_____
Diameter	_____	_____
Bearing	_____	_____
Distance	_____	_____

○ = Corner

**Subsequent Corner Restoration**  
 Year surveyed 1916 By E. B. Horst  
 Location filed COUNTY SURVEY RECORD BOOK 8 P. 124-127  
 Monument FIND OLD GOVT POSTS B. 15' STUMP 7" TAM  
N29E 28 LKS 9" DRY TAM. N37W 17 LKS SET OAK POST  
1917 - E. B. HORST - COUNTY BOOK 8 P. 82 SET 2x48" TAM.  
1916 - also on micro film Roll 105 BK 56 P 9-10

**Bearing Trees, Reference Objects**

Species	<u>W. PINE STUMP</u>	<u>N. PINE STUMP</u>	<u>POPLAR STUMP</u>
Diameter	<u>10"</u>	<u>10"</u>	<u>6"</u>
Bearing	<u>N45E</u>	<u>N25W</u>	<u>NORTH</u>
Distance	<u>9.3'</u>	<u>8.0'</u>	<u>3.50'</u>

1916 ties

**Evidence of Subsequent Corner Restoration**  
 Year of search \_\_\_\_\_ By \_\_\_\_\_

**Bearing Trees, Reference Objects**

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

**Subsequent Corner Restoration**  
 Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
 Location filed \_\_\_\_\_  
 Monument \_\_\_\_\_

**Evidence of Subsequent Corner Restoration Found**  
 Year of search \_\_\_\_\_ By \_\_\_\_\_