


T. 140 R. 28 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
NE 28 Corner common to sections 21, 22, 27, 28



O = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1870

Original monument POST

| Bearing Trees |               |               |               |                |
|---------------|---------------|---------------|---------------|----------------|
| Species       | <u>TAM.</u>   | <u>TAM.</u>   | <u>TAM.</u>   | <u>W. PINE</u> |
| Diameter      | <u>16"</u>    | <u>8"</u>     | <u>19"</u>    | <u>20"</u>     |
| Bearing       | <u>N 60 E</u> | <u>S 25 E</u> | <u>S 80 W</u> | <u>N 39 W</u>  |
| Distance      | <u>48 LKS</u> | <u>43 LKS</u> | <u>22 LKS</u> | <u>43 LKS</u>  |

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_

Monument found \_\_\_\_\_

Original Bearing Trees Found

|          |       |       |       |       |
|----------|-------|-------|-------|-------|
| Species  | _____ | _____ | _____ | _____ |
| Diameter | _____ | _____ | _____ | _____ |
| Bearing  | _____ | _____ | _____ | _____ |
| Distance | _____ | _____ | _____ | _____ |

Subsequent Corner Restoration

Year surveyed 1913 By GLO (LES CLEMENT)

Location filed OFFICE OF SURVEYOR GENERAL (U.S.)

Monument FIND NE & SW BITS DEAD AND STUMPS OF  
SE & SW SET 4" X 6" TAM POST.  
1920, BEN CLARK, BOOK "C" P 560 FIND I.M.

Evidence of Subsequent Corner Restoration

Year of search 1947 By JOHN CURO

COUNTY BOOK "D" P 325 I.M.

1939 - CCC - Washburn Lake - BK # 13 P. 16.  
at 5280' from South - set app. sec cor.

1941 - BK 14 P. 6 - at 5280' from S - set app. cor.

Bearing Trees, Reference Objects

| Bearing Trees, Reference Objects |                   |                   |                  |               |
|----------------------------------|-------------------|-------------------|------------------|---------------|
| Species                          | <u>SPRUCE</u>     | <u>SPRUCE</u>     | <u>SPRUCE</u>    | <u>SPRUCE</u> |
| Diameter                         | <u>8"</u>         | <u>8"</u>         | <u>6"</u>        | <u>8"</u>     |
| Bearing                          | <u>N 24 E</u>     | <u>S 66 E</u>     | <u>S 49-30 W</u> | <u>N 25 W</u> |
| Distance                         | <u>35 1/2 LKS</u> | <u>30 1/2 LKS</u> | <u>33 LKS</u>    | <u>17 LKS</u> |

1913 TIES.

Bearing Trees, Reference Objects

| Bearing Trees, Reference Objects |                  |               |                  |                  |
|----------------------------------|------------------|---------------|------------------|------------------|
| Species                          | <u>SPRUCE</u>    | <u>SPRUCE</u> | <u>SPRUCE</u>    | <u>SPRUCE</u>    |
| Diameter                         | <u>10"</u>       | <u>14"</u>    | <u>7"</u>        | <u>14"</u>       |
| Bearing                          | <u>N 57-42 E</u> | <u>S 38 E</u> | <u>S 50-30 W</u> | <u>N 70-30 W</u> |
| Distance                         | <u>9.78'</u>     | <u>44.20'</u> | <u>27.60'</u>    | <u>22.52'</u>    |

1947 TIES

R-13

Subsequent Corner Restoration

Year surveyed 1915 By H.F. Ballwin

Location filed Microfilm - roll 105 BK 61 P. 42

Monument Find corner P. 47 set standard I.M.  
- no new ties as old BITS are good

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_

PLAT - WABEDA PASS

JOHN CURO 1915