


Index No. R 6-7

CASS COUNTY LAND CORNER RECORD

T. 140 R. 28 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
MC# 48 Corner common to sections 20, 29



EXISTING SURVEYS

Original Government Survey

Year surveyed 1870  
Original monument POST

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

Bearing Trees	
Species <u>N. PINE</u>	<u>N. PINE</u>
Diameter <u>20"</u>	<u>16"</u>
Bearing <u>S 61° W</u>	<u>N 5° W</u>
Distance <u>40 LKS</u>	<u>32 LKS</u>

Original Bearing Trees Found

Species _____	_____
Diameter _____	_____
Bearing _____	_____
Distance _____	_____

Subsequent Corner Restoration

Year surveyed Mar 2002 By CCSO  
Location filed \_\_\_\_\_  
Monument MC #48 Found 2 1/4" ODIP, up 60'  
4' W. of water.

Evidence of Subsequent Corner Restoration

Year of search \_\_\_\_\_ By \_\_\_\_\_

Bearing Trees, Reference Objects

Species <u>N. PINE</u>	<u>Pine stump</u>	<u>N. PINE</u>
Diameter <u>14"</u>		<u>14"</u>
Bearing <u>N 15° W</u>	<u>N 30° W</u>	<u>S 35° W</u>
Distance <u>40.96'</u>	<u>22'</u>	<u>55.65'</u>

Bearing Trees, Reference Objects

_____	_____	_____
_____	_____	_____
_____	_____	_____
_____	_____	_____

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_

Remonumentation certificate prepared \_\_\_\_\_

By \_\_\_\_\_

Filed at \_\_\_\_\_

Date \_\_\_\_\_