


Index No. T 21

CASS COUNTY LAND CORNER RECORD

T. 140 R. 28 M. 5th Coordinates: X _____ Y _____
E 1/4 26 Corner common to sections 25, 26



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1870
Original monument Post

Original Evidence Found

Year of search _____ By _____
Monument found _____

Bearing Trees

Species DRY SPRUCE
Diameter 3'
Bearing S77W
Distance 23 LKS.

Original Bearing Trees Found

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed 1922 By BEN CLARK
Location filed COUNTY RESURVEY 'E-14'
Monument IRON MONUMENT

Evidence of Subsequent Corner Restoration

Year of search 1939 By CCC
Washburn Lake - BK# 12 P. 3
at 2640' from S. 1/4 (Approx) falls in road.
Set approx cor. at 2646'
8941 - BK# 14 P. 3 at 2640' from South - set
approx cor.

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Bearing Trees, Reference Objects

Subsequent Corner Restoration

Year surveyed 2000 By CCSO
Location filed Cass Co. Survey Dept.
Monument Set a P.K. from calc. position,
Located at & C.R. 54.

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

REF TIES:

5" Tamarack N 46°E 48.23'
7" Spruce S 85°E 94.82'
10" W. Oak S 19°W 97.54'

* distance meas. to dbl. hd. nail

Remonumentation certificate prepared _____ By _____
Filed at _____ Date _____