


Index No. V 21

CASS COUNTY LAND CORNER RECORD

T. 140 R. 20 M. 5th Coordinates: X _____ Y _____
NE 35 Corner common to sections 25, 26, 35, 36



EXISTING SURVEYS

Original Government Survey

Year surveyed 1870

Original monument Post

Species	Bearing	Trunks	Trunks
<u>POPULAR</u>	<u>POPULAR</u>	<u>POPULAR</u>	<u>POPULAR</u>
Diameter <u>8"</u>	<u>8"</u>	<u>10"</u>	<u>8"</u>
Bearing <u>N50W</u>	<u>S49W</u>	<u>S45E</u>	<u>N82E</u>
Distance <u>40 LKS</u>	<u>23 LKS</u>	<u>22 LKS</u>	<u>26 LKS</u>

Original Evidence Found

Year of search _____ By _____

Monument found _____

Original Bearing Trees Found

Species _____

Diameter _____

Bearing _____

Distance _____

Subsequent Corner Restoration

Year surveyed 1922 By BEN CLARK

Location filed COUNTY RESURVEY "E-14"

Monument 1 ROW MONUMENT

Evidence of Subsequent Corner Restoration

Year of search 1939 By CCC

Washburn Lake - BK# 12 P. 2

at 5325' from S- l.p. 15 12.6' east

BK# 13 P. 11 Start west from corner

1941 BK# 14 P. 2 at 5312' from S. Fnd 2" l.p. 11.5' east of line

Bearing Trees, Reference Objects

Species _____

Diameter _____

Bearing _____

Distance _____

Bearing Trees, Reference Objects

Species _____

Diameter _____

Bearing _____

Distance _____

Subsequent Corner Restoration

Year surveyed _____ By _____

Location filed _____

Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search 2000 By CCSO

Fnd. impl. 2" ODIP up 1.5' Good cond.

Fnd. B.T. w/ DNR tag on face.

REF. TIES:

<u>8" W. Oak</u>	<u>S 82° W</u>	<u>67.96'</u>
<u>10" W. Oak</u>	<u>N 24° E</u>	<u>28.68'</u>
<u>15" R. Oak</u>	<u>S 82° E</u>	<u>54.60'</u>
<u>(TAG) 6" Spruce</u>	<u>S 36° E</u>	<u>35.87'</u>

March 2005 P. Trotter #41002

Cert. of Survey shows monument found

Remonumentation certificate prepared _____ By _____

Filed at _____ Date _____