


Index No. V-W 9

CASS COUNTY LAND CORNER RECORD

T. 140 R. 28 M. 5TH Coordinates: X _____ Y _____
MC# 11 Corner common to sections 32, 33



EXISTING SURVEYS

Original Government Survey

Year surveyed 1870
Original monument Post

| Species | Bearing | Trees |
|---------------|---------------|-------|
| <u>W. AWE</u> | <u>OAK</u> | |
| <u>18"</u> | <u>10"</u> | |
| <u>N85W</u> | <u>N49E</u> | |
| <u>19 LKS</u> | <u>43 LKS</u> | |

Original Evidence Found

Year of search _____ By _____
Monument found _____

Original Bearing Trees Found

| Species | Diameter | Bearing | Distance |
|---------|----------|---------|----------|
| | | | |
| | | | |
| | | | |
| | | | |

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration

Year of search 1998 By Langbecker & Assoc
Survey info indicates found 2" IP
at lake down very old fence line.

Bearing Trees, Reference Objects

| Species | Diameter | Bearing | Distance |
|---------|----------|---------|----------|
| | | | |
| | | | |
| | | | |
| | | | |

Bearing Trees, Reference Objects

| Species | Diameter | Bearing | Distance |
|---------|----------|---------|----------|
| | | | |
| | | | |
| | | | |
| | | | |

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
PLAT - TOWA POINT
JOHN M. GREANE 1927 - IRON - NOT LABELED M.C.

Remonumentation certificate prepared _____ By _____
Filed at _____ Date _____