


Index No. X 25

CASS COUNTY LAND CORNER RECORD

T. 140 R. 28 M. 5TH Coordinates: X _____ Y _____
E 1/4 36 Corner common to sections 36 AND 31 - 140-27



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1863
Original monument POST

Bearing Trees

Species	<u>ASH</u>	<u>ASPEN</u>	_____
Diameter	<u>4"</u>	<u>12"</u>	_____
Bearing	<u>N27E</u>	<u>S43W</u>	_____
Distance	<u>18 LKS.</u>	<u>38 LKS.</u>	_____

Original Evidence Found

Year of search _____ By _____
Monument found _____

Original Bearing Trees Found

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1939 By CCC
Location filed Washburn Lake - BK # 13 P. 1
Monument at 2640' from South - Set app. 1/4 cor.

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

Bearing Trees, Reference Objects

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Bearing Trees, Reference Objects

_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Remonumentation certificate prepared _____ By _____
Filed at _____ Date _____