


Index No. C17

CASS COUNTY LAND CORNER RECORD

T. 140 R. 29 M. 5TH Coordinates: X _____ Y _____
E 1/4 3 Corner common to sections 2,3



EXISTING SURVEYS

Original Government Survey

Year surveyed 1870
Original monument POST
Notes show corner at north edge of swamp

Bearing Trees

Species Spruce Dead Pine Dead Pine
Diameter 10" 14" 20"
Bearing S70E N54E N85W
Distance 10 lks 40 lks 15 lks

Original Evidence Found

Year of search _____ By _____
Monument found _____

Original Bearing Trees Found

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed 1915 By JOHN CYRO
Location filed COUNTY RESURVEY "E-23"
Monument 2 1/4 x 4 8" IRON MONUMENT
1915, FA DENVER, BOOK "E" P. 241 SET CORNER. P. 242 2x48"
ZIM. w/ CAD.
also on microfilm - roll 1105 BK 66 P. 64

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

Bearing Trees, Reference Objects

Subsequent Corner Restoration

Year surveyed 1966 By R. F. Schneider
Location filed _____
Monument Capped Iron

Ties: 7" Twin R. Oak S22 1/2 E 14.5'
7" R. Oak S88 E 21.9'

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Remonumentation certificate prepared _____ By _____
Filed at _____ Date _____