Index No. C21

CASS COUNTY LAND CORNER RECORD

T. 140 R. 29 M. 5TH Coordinates: X _____ Y _____
E 1/4 2 Corner common to sections 12



EXISTING SURVEYS

Original Government Survey

Year surveyed 1870
Original monument POST
NOTES SHOW COR. ON NORTH EDGE OF SWAMP

Bearing Trees

Species	Spruce			
Diameter	10"			
Bearing	S70E			
Distance	10 lks.			

Original Evidence Found

Year of search _____ By _____
Monument found _____

Original Bearing Trees Found

Species				
Diameter				
Bearing				
Distance				

Subsequent Corner Restoration

Year surveyed 1915 By JOHN CURD
Location filed COUNTY RESURVEY "E-23"
Monument 2 1/4 x 48" IRON MONUMENT
1915, F.A. DONNER, COUNTY BOOK "C" P. 236 FND GOVT
B.T: 10" SPRUCE S70E 10 LKS SET 4x4x48" CEDAR POST.
also on microfilm - roll 105 BK 66 P. 35

Bearing Trees, Reference Objects

Species				
Diameter				
Bearing				
Distance				

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

Bearing Trees, Reference Objects

Subsequent Corner Restoration

Year surveyed 1973 By R.F. Schneider
Location filed
Monument Found 2" CGP

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Plat - Lantern Bay Subdivision
Roger Mustonen 1981

Remonumentation certificate prepared _____ By _____
Filed at _____ Date _____