


Index No. E 11

CASS COUNTY LAND CORNER RECORD

T. 140 R. 29 M. 5TH Coordinates: X _____ Y _____
N 1/4 9 Corner common to sections 4, 9



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1870
Original monument POST

Original Evidence Found

Year of search _____ By _____
Monument found _____

Bearing Trees

Species W. Pine Maple _____
Diameter 24" 6" _____
Bearing N75W S30E _____
Distance 25 lks 23 lks. _____

Original Bearing Trees Found

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed 1919 By E.B. Horst
Location filed COUNTY BOOK "C" P. 156
Monument FIND CURR'S WOOD POST - SET 2X48" I.M.

Evidence of Subsequent Corner Restoration

Year of search 1911 By Harry Todd
micro film - roll 105 BK 69 P. 63
established corner.

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Bearing Trees, Reference Objects

Subsequent Corner Restoration

Year surveyed 1972 By Bruce A. Foltz #9232
Location filed _____
Monument 1 1/2 iron pipe set by Bill Spain
down 0.6' in road

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
PLAT - CEDAR GROVE BEACH
ROBERT C. JOHNSON 1927

1965 - P.F. Schneider

Found pipe in road

Trees: 14" N. Pine S47E 57.9'
12" Spruce S19 1/2 W 74.0'

Remonumentation certificate prepared _____

By _____

Filed at _____

Date _____