


Index No. L 9

CASS COUNTY LAND CORNER RECORD

T. 140 R. 29 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
E 1/4 17 Corner common to sections 16, 17



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1870  
Original monument POST

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

Bearing Trees	
Species <u>J. Pine</u>	<u>J. Pine</u>
Diameter <u>6"</u>	<u>7"</u>
Bearing <u>N 65 E</u>	<u>N 63 W</u>
Distance <u>14 lks.</u>	<u>10 lks.</u>

Original Bearing Trees Found			
Species _____	_____	_____	_____
Diameter _____	_____	_____	_____
Bearing _____	_____	_____	_____
Distance _____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1927 By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument CO DITCH SURVEY BK 161 BOX 3 OF  
CO. DITCH SURVEY BOOKS, PG 5

Evidence of Subsequent Corner Restoration

Year of search 1987 By Dave Landecker  
Corner (Certificate - Doc # 302272)  
Found 3/4" l.p. used by others

Bearing Trees, Reference Objects

Species _____	_____	_____	_____
Diameter _____	_____	_____	_____
Bearing _____	_____	_____	_____
Distance _____	_____	_____	_____

Bearing Trees, Reference Objects

<u>Red oak</u>	<u>Burr oak</u>	<u>White</u>	<u>Balsam</u>
<u>9"</u>	<u>4"</u>	<u>4"</u>	<u>14"</u>
<u>N 15 E</u>	<u>S 82 E</u>	<u>S 28 E</u>	<u>N 83 W</u>
<u>27.47'</u>	<u>32.18'</u>	<u>14.27'</u>	<u>9.23'</u>

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_  
Feb 1988 D Landecker #17008  
Cert. of Survey shows monument found

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Certificate - Dave Landecker 1987

Remonumentation certificate prepared \_\_\_\_\_ By \_\_\_\_\_  
Filed at \_\_\_\_\_ Date \_\_\_\_\_