


Index No. Q-R 17

CASS COUNTY LAND CORNER RECORD

T. 140 R. 29 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
AC# 44 Corner common to sections 22, 23



EXISTING SURVEYS

Original Government Survey

Year surveyed 1870  
Original monument POST

Bearing Trees

Species W. Pine  
Diameter 24"  
Bearing S 48 W  
Distance 25 lks.

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

Original Bearing Trees Found

Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Subsequent Corner Restoration

Year surveyed 1960 By BC-M  
Location filed Sec. of State  
Monument Fd. remains of original BT - fallen  
badly decayed w. pine with old ax marks  
and scar on NE side.

Bearing Trees, Reference Objects

Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Evidence of Subsequent Corner Restoration

Year of search 1967 By R.F. Schneider  
Found oak stake.

Bearing Trees, Reference Objects

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_

DNR FILE - Start of Certificate  
1992 Cert. Filed by John Walker / DNR  
Doc. # 343677  
Found 1/2" iron pipe with RLS # 12684.  
Ties: 7" Maple N 75 E 19.91'; 6" B. Oak  
5.34 E 19.61'; 12" R. OAK S 23 W 25.06'

July 2003 R. Mustonen # 11946  
Cert. of Surv. shows Mon. Found

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

Remonumentation certificate prepared \_\_\_\_\_ By \_\_\_\_\_  
Filed at \_\_\_\_\_ Date \_\_\_\_\_ Sc 607 2018  
925.64