


Index No. R 13

CASS COUNTY LAND CORNER RECORD

T. 140 R. 29 M. 5th Coordinates: X _____ Y _____
NE 28 Corner common to sections 21, 22, 27, 28



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1870
Original monument POST

Original Evidence Found

Year of search _____ By _____
Monument found _____

Species	Bearing	Trees	
<u>D. Tam</u>	<u>D. Tam</u>	<u>D. Tam</u>	<u>D. Tam</u>
<u>4"</u>	<u>4"</u>	<u>6"</u>	<u>5"</u>
<u>NSE</u>	<u>NSW</u>	<u>S67E</u>	<u>S1W</u>
<u>27 lks</u>	<u>25 lks</u>	<u>15 lks</u>	<u>9 lks.</u>

Original Bearing Trees Found

Species	Diameter	Bearing	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

Bearing Trees, Reference Objects

Species	Diameter	Bearing	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Bearing Trees, Reference Objects

Species	Diameter	Bearing	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

(OVER)

R-13

Subsequent Corner Restoration

Year surveyed 1966 By R.F. Schneider
Location filed _____
Monument Found old post and set new oak post.

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
PLAT - CEDAR SHARES
R.F. SCHNEIDER 1970 #

1970 - replaced post with 3" pipe
1966 - R.F. Schneider - Survey for Dept of Nat. Resources - Map in file
1/04 - CCSO found 3" ODIP, up 1.3', 220' E into swamp, no trees near.

Feb. 1988 D Handecker #17008
Cert. of Survey indicates monument found

Remonumentation certificate prepared _____

By _____

Filed at _____

Date _____