


Index No. R3

CASS COUNTY LAND CORNER RECORD

T. 140 R. 29 M. 5th Coordinates: X _____ Y _____
N 1/4 30 Corner common to sections 19, 30



O = Corner

EXISTING SURVEYS

Original Government Survey
Year surveyed 1870
Original monument POST

Original Evidence Found
Year of search _____ By _____
Monument found _____

Bearing Trees
Species N. Pine Dead Birch
Diameter 9" 6"
Bearing S50E N22W
Distance 50 lks. 11 lks.

Original Bearing Trees Found
Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration
Year surveyed 1907 By JOHN CRO
Location filed COUNTY BOOK B P. 433-441
Monument FIND OLD GOVT BIT: Down 9" N. Pine S50E
50 lks.

Evidence of Subsequent Corner Restoration
Year of search 1999 By CCSO
Find in place 2 1/2" OD IP in concrete w/ fence-
post guard also in concrete. Located 26' N of N/S
fence line and 31' S of E.C.R. 5.

Bearing Trees, Reference Objects
Species _____
Diameter _____
Bearing _____
Distance _____

Bearing Trees, Reference Objects
Twin Cedar P. Pole Balsam
9" 4"
N 52° W S 80° E S 15° W
88.71' 106.44' 24.27'
* distance pulled to dbl. hd. nail

NOTE: RFS files show owner lost: does not agree with C. E. COULTER Subsequent Corner Restoration

Year surveyed 1978 By R. F. Schneider
Location filed _____
Monument 2 1/2" Pipe in concrete

R-3 Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
PLAT - SHARES OF SUMMER ADDITION
R.F. SCHNEIDER 1968

Remonumentation certificate prepared A000667180
Filed at _____

By _____
Date _____