


Index No. V 5-6

CASS COUNTY LAND CORNER RECORD

T. 140 R. 29 M. 5th Coordinates: X _____ Y _____
MC # 54 Corner common to sections 29, 32



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1870
Original monument POST

Original Evidence Found

Year of search _____ By _____
Monument found _____

Bearing Trees

Species	<u>W. Birch</u>	<u>W. Birch</u>	_____	_____
Diameter	<u>6"</u>	<u>4"</u>	_____	_____
Bearing	<u>S2SW</u>	<u>N62E</u>	_____	_____
Distance	<u>6 lks.</u>	<u>3 lks.</u>	_____	_____

Original Bearing Trees Found

Species	_____	_____	_____	_____
Diameter	_____	_____	_____	_____
Bearing	_____	_____	_____	_____
Distance	_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration

Year of search 1987 By Dave Landecker
Corner Certificate - Doc # 302276
End 1 1/4" I.P. 6'E. of Lake

Bearing Trees, Reference Objects

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Bearing Trees, Reference Objects

<u>W. Pine</u>	<u>Red oak</u>	<u>N. Pine</u>
<u>21"</u>	<u>4"</u>	<u>28"</u>
<u>N38E</u>	<u>S10E</u>	<u>S27W</u>
<u>10.66'</u>	<u>16.05'</u>	<u>14.04'</u>

V-5,6

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
Certificate - Dave Landecker - 1987

Remonumentation certificate prepared _____

By _____

Filed at _____

Date _____