


T. 140 R. 30 M. 5th Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
m/c # 1 Corner common to sections 13 AND 18 - 140-29



O = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1865  
Original monument POST

Species	Bearing	Trees
<u>Aspen</u>	<u>BIRCH</u>	
<u>10"</u>	<u>8"</u>	
<u>563W</u>	<u>546 1/2 E</u>	
<u>51 LKS</u>	<u>34 LKS</u>	

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

Original Bearing Trees Found

Species	Bearing	Distance
_____	_____	_____
_____	_____	_____
_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1907 By JOHN CURE  
Location filed COUNTY BOOK "B" P. 433-441  
Monument FND 1 BIRCH B.T.  
1916, E.B. HORST - BOOK "B" P. 557 SET 2 1/2 KYE "  
CAPPED I.M. also on micro film - roll 105 BX 61 P. 150  
1919 - E.B. HORST, BOOK "C" P. 204 FND I.M.

Bearing Trees, Reference Objects

Species	Bearing	Distance
_____	_____	_____
_____	_____	_____
_____	_____	_____

Evidence of Subsequent Corner Restoration

Year of search 1965 By R.F. SCHNEIDER  
COUNTY BOOK "D" P. 442 FND CAPPED I.M.

Bearing Trees, Reference Objects

Species	Bearing	Distance
_____	_____	_____
_____	_____	_____
_____	_____	_____

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
PLAT - WEBB LAKE TERRACE  
W. J. SPAIN 1959 IRON - NOT LABELED M.C.

DNR SURVEY - TIES TO 2" PIPE IN TOWNSHIP PLAT

FILE	<u>2" Br. oak</u>	<u>50°</u>	<u>13.78'</u>
1981	<u>P.P.</u>	<u>152°</u>	<u>20.08'</u>
	<u>2" Ash</u>	<u>285°</u>	<u>3.89'</u>

CERT. BY DNR. 1990  
DOC. # 334963

Fnd. incl. 2 1/2" ODIP up 1.8'. Located 83' ± N.  
of E CSAH 5 on extension of N/S TWR RD.  
WOODROW 1. Pipe is 12' S of Webb Lk. shoreline.

REF. TIES:

<u>8" Twin P. Oak</u>	<u>N 62° W</u>	<u>9.66'</u>
<u>P. Pole</u>	<u>S 33° E</u>	<u>19.58'</u>

May 2003 T. Freeman # 21367  
Cert. of Surv. shows Mon. Found