


Index No. R 15

CASS COUNTY LAND CORNER RECORD

T. 140 R. 30 M. 5th Coordinates: X _____ Y _____
N/427 Corner common to sections 22, 27



○ = Corner

EXISTING SURVEYS

Original Government Survey
 Year surveyed 1865
 Original monument Post

Bearing Trees
 Species Bl. Pine N. Pine
 Diameter 9" 9"
 Bearing N3 1/2 W S43 1/2 E
 Distance 28 CKS 8 LKS

Original Evidence Found
 Year of search _____ By _____
 Monument found _____

Original Bearing Trees Found
 Species _____
 Diameter _____
 Bearing _____
 Distance _____

Subsequent Corner Restoration

Year surveyed 1939 By JOHN CURD
 Location filed COUNTY BOOK D' P. 198
 Monument Iron 2x36" I.P. Set by CURD FROM OLD GOVT BITS.

Evidence of Subsequent Corner Restoration
 Year of search 1965 By R.F. SCHNEIDER
COUNTY BOOK D' P 467 IRON PIPE - NEW TIES.

Bearing Trees, Reference Objects

Species	J. Pine	J. Pine STUMP	J. Pine STUMP	J. Pine
Diameter	10"	8"	9"	14"
Bearing	N47-20E	N33-48W	S47-20W	S35-50E
Distance	94.65'	59.55'	47.55'	77.95'

Bearing Trees, Reference Objects

Species	J. Pine	MAPLE	J. Pine	N. Pine
Diameter	10"	8"	10"	12"
Bearing	S60W	N76E	S46E	N35E
Distance	52.4'	64.0'	87.9'	127.85'

R-15

Subsequent Corner Restoration

Year surveyed 1972 By Co Hwy Dept.
 Location filed Co. RD # 45
 Monument 2" I.P. in place
Maple 6" - NE 102.2'
J. Pine 12" SE 88.5'
J. Pine 10" ESE 62.2'

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
PLAT - LAUGESONS PLEASANT VIEW
WALTER CURD 1975
Oct 2003 M. Landwehr # 7452
Cent. of Svy. shows Mon. Found

1999 - CCSO

Set P.K. nail from ties. Orig. Pipe removed for construction. Located at 1/2 C.R.D. 45 and 3' S of fe. line to the East.

9" Aspen	N 74° W	67.25'
12" Maple clump	N 79° E	64.82'
1/2" PIN	N 55° E	61.55'
12" N. Pine	S 42° E	90.88'
10" J. Pine	S 21° W	142.35'
1/2" PIN	S 30° W	56.41'

Remonumentation certificate prepared _____
 Filed at _____

By _____
 Date _____