


Index No. T 5

CASS COUNTY LAND CORNER RECORD

T. 140 R. 30 M. 5TH Coordinates: X _____ Y _____
E 1/4 30 Corner common to sections 29, 30



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1865
Original monument BST

Original Evidence Found

Year of search _____ By _____
Monument found _____

Bearing Trees	
Species <u>N. PINE</u>	<u>N. PINE</u>
Diameter <u>24"</u>	<u>15"</u>
Bearing <u>S74E</u>	<u>S52W</u>
Distance <u>59 LKS</u>	<u>46 LKS</u>

Original Bearing Trees Found

Species _____	_____
Diameter _____	_____
Bearing _____	_____
Distance _____	_____

Subsequent Corner Restoration

Year surveyed 1965 By R. E. SCHNEIDER
Location filed COUNTY BOOK D P. 452
Monument IRON PIPE - (NEW TIES)

Evidence of Subsequent Corner Restoration

Year of search 1924 By Minn. Hur Dept.
R/W map in Recorder's office - Lot trap to Pine River
Hub at fence corner 468.8' E of 4

Bearing Trees, Reference Objects

Species <u>ROAK</u>	<u>ROAK</u>	<u>ROAK</u>
Diameter <u>6"</u>	<u>6"</u>	<u>6"</u>
Bearing <u>N5W</u>	<u>N31E</u>	<u>N88W</u>
Distance <u>23.65'</u>	<u>14.6'</u>	<u>28.65'</u>

Bearing Trees, Reference Objects

_____	_____
_____	_____
_____	_____
_____	_____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
PLAT - HILLCREST CEMETERY
JOHN M. GREEN 1923
Certificate - Jim Nielson - Minn DOT 1983
Doc. # 267932
Found 1" pinched pipe. Set MN/DOT
cast iron monument. TIES: 10" Twin
Red Oak N40W 15.38'; 6" Red Oak N88W
28.65'; 6" Red Oak N88W 28.65'; 6" Red
Oak S60W 32.38'; 6" Red Oak NSW 23.65';
6" Red Oak N31E 14.6'; 10" Birch S85E
12.44'.

Re monumentation certificate prepared _____

By _____

Filed at _____

Date _____