


Index No. V 13-14

CASS COUNTY LAND CORNER RECORD

T. 140 R. 30 M. 5TH Coordinates: X _____ Y _____
M.C.# 29 Corner common to sections 27, 34



EXISTING SURVEYS

Original Government Survey

Year surveyed 1865
Original monument POST

Original Evidence Found

Year of search _____ By _____
Monument found _____

Bearing Trees

Species	<u>DL. PINE</u>	<u>N. PINE</u>	_____	_____
Diameter	<u>10"</u>	<u>5"</u>	_____	_____
Bearing	<u>N1/2W</u>	<u>S82E</u>	_____	_____
Distance	<u>24 LKS</u>	<u>68 LKS</u>	_____	_____

Original Bearing Trees Found

Species	_____	_____	_____	_____
Diameter	_____	_____	_____	_____
Bearing	_____	_____	_____	_____
Distance	_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1999 By CCSO
Location filed CCSO Job # 98031
Monument Fd. 1 3/4" OD IP, up 0.3', 22' S of
E drive at waters edge.

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

Bearing Trees, Reference Objects

Species	<u>R. Pine</u>	<u>Iron Pipe</u>	<u>R. Pine</u>	<u>SE Cor</u>
Diameter	<u>12"</u>	<u>1 3/4"</u>	<u>11"</u>	<u>Cabin</u>
Bearing	<u>N62°W</u>	<u>N23°W</u>	<u>N10°W</u>	<u>N44°E</u>
Distance	<u>79.28*</u>	<u>95.18</u>	<u>71.84*</u>	<u>58.41</u>

Bearing Trees, Reference Objects

Species	_____	_____	_____	_____
Diameter	_____	_____	_____	_____
Bearing	_____	_____	_____	_____
Distance	_____	_____	_____	_____

* distance to dbl. hd. nail

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Remonumentation certificate prepared _____

By _____

Filed at _____

Date _____