


Index No. A-7,8

CASS COUNTY LAND CORNER RECORD

T. 140N R. 31W M. 5th Coordinates: X _____ Y _____
MC # 30 Corner common to sections 5 & 32/141/31



o = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1864

Original monument Post

Bearing Trees	
Species <u>W. Pine</u>	<u>Aspen</u>
Diameter <u>10"</u>	<u>6"</u>
Bearing <u>S 30° W</u>	<u>N 9° W</u>
Distance <u>103</u>	<u>105</u>

Original Evidence Found

Year of search _____ By _____

Monument found _____

Original Bearing Trees Found

Species	Diameter	Bearing	Distance

Subsequent Corner Restoration

Year surveyed _____ By _____

Location filed _____

Monument _____

Evidence of Subsequent Corner Restoration

Year of search 11/2000 By CCSO

Found 2" iron pipe with Brass cap
up 17', PLS # 12266, 20'± W. of Lake
149'± E. of Q Co. Rd #71

Bearing Trees, Reference Objects

Species	Diameter	Bearing	Distance

Bearing Trees, Reference Objects

Species	Diameter	Bearing	Distance
<u>R. Oak</u>	<u>6"</u>	<u>N 13° W</u>	<u>27.13' *</u>
<u>Birch</u>	<u>8"</u>	<u>N 33° E</u>	<u>1.97' *</u>
<u>Birch</u>	<u>10"</u>	<u>S 52° W</u>	<u>9.26' *</u>
<u>Sign Post</u>	<u>Steel</u>	<u>West</u>	<u>3.9'</u>

* denotes 16d galv. nail

Subsequent Corner Restoration

Year surveyed _____ By _____

Location filed _____

Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Remonumentation certificate prepared _____ By _____
Filed at _____ Date _____