


Index No. E5

CASS COUNTY LAND CORNER RECORD

T. 140 R. 31 M. 5TH Coordinates: X _____ Y _____
NE 7 Corner common to sections 5, 6, 7, 8



EXISTING SURVEYS

Original Government Survey
Year surveyed 1870
Original monument POST

Original Evidence Found
Year of search _____ By _____
Monument found _____

Species	Bearing	Trees
<u>ASPEN</u>	<u>S.P. PINE</u>	<u>ASPEN</u>
Diameter <u>12"</u>	<u>6"</u>	<u>6"</u>
Bearing <u>N 31 E</u>	<u>N 47 W</u>	<u>S 60 W</u>
Distance <u>54 LKS</u>	<u>27 LKS</u>	<u>39 LKS.</u>

Species	Diameter	Bearing	Distance
Original Bearing Trees Found			
Species _____	_____	_____	_____
Diameter _____	_____	_____	_____
Bearing _____	_____	_____	_____
Distance _____	_____	_____	_____

Subsequent Corner Restoration
Year surveyed 1990 By LANDCKER
Location filed _____
Monument 2" x 36" TELESPAP Co. Mon.

Evidence of Subsequent Corner Restoration
Year of search _____ By _____

SET 6' STEEL SIGN POST, NORTH 2.0'
CERTIFICATE DOC. # 325137

Species	Bearing	Trees, Reference Objects
<u>N. PINE</u>	<u>MAPLE</u>	<u>W. OAK</u> <u>W. OAK</u>
Diameter <u>21</u>	<u>6</u>	<u>6</u> <u>5</u>
Bearing <u>N 29 W</u>	<u>N 15 E</u>	<u>S 32 E</u> <u>S 60 W</u>
Distance <u>36.46</u>	<u>35.20</u>	<u>8.44</u> <u>21.25</u>

Bearing Trees, Reference Objects

Subsequent Corner Restoration
Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found
Year of search _____ By _____
CERT. BY LANDCKER 1990
DOC. # 325137

Remonumentation certificate prepared _____
Filed at _____

By _____
Date _____