


Index No. J 1314

CASS COUNTY LAND CORNER RECORD

T. 140 R. 31 M. 5TH Coordinates: X _____ Y _____
MC# 24 Corner common to sections 10, 15



EXISTING SURVEYS

Original Government Survey

Year surveyed 1870
Original monument POST

Original Evidence Found

Year of search _____ By _____
Monument found _____

Species	Bearing	Trees
<u>W. PINE</u>	<u>ASPEN</u>	
Diameter <u>24"</u>	<u>6"</u>	
Bearing <u>N45E</u>	<u>S10W</u>	
Distance <u>43 LKS</u>	<u>20 LKS</u>	

Original Bearing Trees Found

Species	Diameter	Bearing	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1915 By N. D. GORMAN
Location filed COUNTY BOOK "B" P 465-468
Monument SET 80 d SPIKE

Evidence of Subsequent Corner Restoration

Year of search 1914 By John Curo
microfilm - roll 115 BK 93 P 139
Set 2x48" l.p. - find roots of NE 8.T.

Bearing Trees, Reference Objects

Species	Diameter	Bearing	Distance
<u>POPULAR</u>	<u>10"</u>	<u>N37-23W</u>	<u>9.90'</u>
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Bearing Trees, Reference Objects

Birch	oak	OLD HOUSE	Birch
<u>20"</u>	<u>3"</u>	<u>corner</u>	<u>2"</u>
<u>S41W</u>	<u>S43E</u>	<u>East</u>	<u>West</u>
<u>45.43'</u>	<u>18.85'</u>	<u>9.0'</u>	<u>1'</u>

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
PLAT - PLAINVIEW BEACH
JOHN M. GREENE 1926

PLAT - PEACEFUL VALLEY
W. J. SPAW JR 1947

PLAT - COUGHLIN BEACH
HAROLD CURO 1956

Remonumentation certificate prepared _____ By _____
Filed at _____ Date _____