


Index No. J 21

CASS COUNTY LAND CORNER RECORD

T. 140 R. 31 M. 5th Coordinates: X _____ Y _____
NE 14 Corner common to sections 11, 12, 13, 14



EXISTING SURVEYS

Original Government Survey

Year surveyed 1870
Original monument lost

Species	Bearing Trees		
	N. PINE	N. PINE	N. PINE
Diameter	12"	12"	10"
Bearing	S 41 1/2 W	N 19 E	S 41 E
Distance	50 LKS	21 LKS	37 LKS

Original Evidence Found

Year of search _____ By _____
Monument found _____

Species	Original Bearing Trees Found		
Diameter			
Bearing			
Distance			

O = Corner

Subsequent Corner Restoration

Year surveyed 1915 By N. D. Gorman
Location filed COUNTY BOOK 'B' P 469-471
Monument Fnd 2 1/4 x 4 8" GALV. I.P. SET BY Curo
1948, HAROLD Curo, BOOK 'D' P 351 Fnd 2 x 4 8" I.P.
w/ CAP BROKEN OFF.

Species	Bearing Trees, Reference Objects			
	W. PINE	N. PINE	N. PINE	J. PINE
Diameter	10"	12"	15"	11"
Bearing	N 32-50 E	S 16-23 E	S 62-56 W	N 66-38 W
Distance	112.10'	62.65'	56.65'	88.10'

Evidence of Subsequent Corner Restoration

Year of search 1920 By GLO
Fnd 2" GAS PIPE
1914 - John Curo - microfilm - roll 115 BK 93 P. 126
Fnd I.P. set previously

RED OAK	Bearing Trees, Reference Objects	
	N. PINE	
8"	10"	
S 4-45 E	S 62-15 W	
110 LKS	88 LKS	

1920 ties

J-21

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____
June 1909, Top rd order shows no survey

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
PLAT - SERLEY'S SHORES
R.F. SCHNEIDER 1967
Nov. 2000 CCSSO
Fnd. in place; 2" ODIP w/ 60d epk in
center, dwn. 0.6'. Located 7' W & Island
View Dr. NW & 20'S & trail west. Top of
pipe is skewed.

REF. TIES:

8" W. Pine	N 34° E	65.41'
P. Pole	S 48° E	32.88'
11" N. Pine	S 20° E	72.89'
18" N. Pine	S 27° W	60.12'

DEC 2002 T. Freeman # 21367
Cert. of Surv shows Man Found

Jun 2003 M. Landecker # 7452
Cert. of Surv shows Man Found

Sept 2003 M. Landecker # 7452
Cert. of Surv. shows Man Found

Remonumentation certificate prepared _____ By _____
Filed at _____ Date _____