


T. 140 R. 31 M. 5TH Coordinates: X 7,18 Y 18
N114 18 Corner common to sections 7,18



EXISTING SURVEYS

Original Government Survey
Year surveyed 1870
Original monument POST

Original Evidence Found
Year of search _____ By _____
Monument found _____

Bearing Trees
Species W. PINE W. PINE
Diameter 20" 20"
Bearing S40E N35W
Distance 10 LKS 36 LKS

Original Bearing Trees Found
Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration
Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration
Year of search 12/2002 By R. Mustonen
Set 1" iron pipe at prorated lost
position, 24.03 W. of rd 3" IP,
54'± S. of trail.
Certificate filed

Bearing Trees, Reference Objects
Species _____
Diameter _____
Bearing _____
Distance _____

Bearing Trees, Reference Objects

<u>W. oak</u>	<u>W. Pine</u>	<u>W. Pine</u>	<u>W. Pine</u>
<u>8"</u>	<u>6"</u>	<u>9"</u>	<u>36"</u>
<u>NW</u>	<u>NE</u>	<u>SSE</u>	<u>W</u>
<u>10.12'</u>	<u>16.30'</u>	<u>3.63'</u>	<u>54'±</u>

J-3

Subsequent Corner Restoration
Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found
Year of search _____ By _____
JUL 1997 L. SCHELLACK
CERT OF SURV SHOWS MON FOUND
Mar 2003 R. Mustonen #11946
Cert of Surv. shows Mon. found

Remonumentation certificate prepared
Filed at CCRO document #464015

By RLS #11946
Date 3/24/03