


Index No. J 5

CASS COUNTY LAND CORNER RECORD

T. 140 R. 31 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
NE 18 Corner common to sections 7, 8, 17, 18



EXISTING SURVEYS

Original Government Survey

Year surveyed 1870  
Original monument POST

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

Species	Bearing		Trass	
	SP. LINE	SP. LINE	SP. LINE	N. LINE
Aspen	4"	6"	10"	10"
Diameter	10"	4"	6"	10"
Bearing	N 35 E	S 45 E	S 55 W	N 19 W
Distance	10 LKS	15 LKS	22 LKS	40 LKS

Original Bearing Trees Found

Species \_\_\_\_\_  
 Diameter \_\_\_\_\_  
 Bearing \_\_\_\_\_  
 Distance \_\_\_\_\_

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration

Year of search 1982 By FREEMAN, OLSON  
FND 1 1/2" IP. UP 1.3'  
4" BR OAK S 74 W 14'  
7" R. OAK S 37 W 19.2'

Bearing Trees, Reference Objects

Species \_\_\_\_\_  
 Diameter \_\_\_\_\_  
 Bearing \_\_\_\_\_  
 Distance \_\_\_\_\_

Bearing Trees, Reference Objects

Species \_\_\_\_\_  
 Diameter \_\_\_\_\_  
 Bearing \_\_\_\_\_  
 Distance \_\_\_\_\_

1-5

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
1989 Cert. Filed by David Landecker  
Doc. # 317226.  
Found 1 1/4" iron pipe and original NW BT.  
Ties: original Norway Pine Stump N 19 W  
26.4'; 6" Maple N 48 W 26.31'; 5" Burr  
Oak S 58 W 14.11'; 8" Red Oak S 37 W  
19.47'; 13" Aspen S 80 E 20.61'; 5"  
Maple N 18 E 34.96'.  
2002 R. Mustonen # 11946  
Cert. of Sur. shows Mon. Found  
Mar. 2003 R. Mustonen # 11946  
Cert. of Sur. shows Mon. Found  
Oct. 1999 T. Miller # 23046  
Cert. of Sur. shows mon. found

Remonumentation certificate prepared \_\_\_\_\_  
Filed at \_\_\_\_\_

By \_\_\_\_\_  
Date \_\_\_\_\_