


Index No. L-M 25

CASS COUNTY LAND CORNER RECORD

T. 140 R. 31 M. 5th Coordinates: X _____ Y _____

MC # 15 Corner common to sections 13 AND 18-140-30



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1865
Original monument POST

Original Evidence Found

Year of search _____ By _____
Monument found _____

Bearing Trees

Species	<u>N. PINE</u>	<u>N. PINE</u>	_____
Diameter	<u>15"</u>	<u>6"</u>	_____
Bearing	<u>N 29 W</u>	<u>S 83 E</u>	_____
Distance	<u>18 LKS</u>	<u>25 LKS</u>	_____

Original Bearing Trees Found

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1915 By JOHN CURO
 Location filed COUNTY RESURVEY "E-36"
 Monument 2 1/4 x 48" I.M. AND GALT B.TS.
BOOK C P 437 - IRON MONUMENT
1915-Molynaux - microfilm - roll 105 BK 59 P. 6
Stone out of place - one GALT B.T. in place

Bearing Trees, Reference Objects

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Evidence of Subsequent Corner Restoration

Year of search 1912 By GLO (WALT HOFFMAN)
FIND 3" WOOD POST AND 13" N. PINE S 83 E 25 LKS,
AND STUMP 20" N. PINE N 71 1/2 W 18 LKS
SET 16 X 10 X 7" GRANITE STONE

Bearing Trees, Reference Objects

<u>J. PINE</u>	_____	_____	_____
<u>9"</u>	_____	_____	_____
<u>N 40 1/2 W</u>	_____	_____	_____
<u>39 LKS</u>	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1926 By _____
 Location filed _____
 Monument Co DITCH SURVEY BK 161 BOX
3 . OF Co DITCH SURVEY BOOKS, PG 1

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
PLAT - PEACEFUL SHORES
JOHN W. CURO 1946
PLAT - FIRST ADDITION TO PEACEFUL SHORES
JOHN W. CURO 1948

Aug 2003 M. Landecker # 7452
Cert. of Surv. shows Mon. found

Remonumentation certificate prepared _____

By _____

Filed at _____

Date _____