


Index No. N 23-24

CASS COUNTY LAND CORNER RECORD

T. 140 R. 31 M. 5TH Coordinates: X _____ Y _____
M.C. # 4 Corner common to sections 13, 24



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1870
Original monument Post

Original Evidence Found

Year of search _____ By _____
Monument found _____

		Bearing Trees	
Species	<u>Aspen</u>	<u>Aspen</u>	_____
Diameter	<u>2"</u>	<u>2"</u>	_____
Bearing	<u>S46W</u>	<u>N51E</u>	_____
Distance	<u>8 LKS</u>	<u>10 LKS</u>	_____

Original Bearing Trees Found			
Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

Bearing Trees, Reference Objects

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Bearing Trees, Reference Objects

_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
PLAT - LIGHTHOUSE POINT
R.F. SCHNEIDER 1972 IRON - NOT LABELED M.C.

Remonumentation certificate prepared _____
Filed at _____

By _____
Date _____