


Index No. N3

CASS COUNTY LAND CORNER RECORD

T. 140 R. 31 M. 5TH Coordinates: X _____ Y _____
N1419 Corner common to sections 18,19



EXISTING SURVEYS

Original Government Survey

Year surveyed 1870
Original monument POST

Original Evidence Found

Year of search _____ By _____
Monument found _____

Species	Bearing	Trees
<u>PINE</u>	<u>DEAD PINE</u>	
Diameter <u>3"</u>	<u>10"</u>	
Bearing <u>55E</u>	<u>NORTH</u>	
Distance <u>34 LKS</u>	<u>160 LKS</u>	

Original Bearing Trees Found

Species	Diameter	Bearing	Distance

O = Corner

Subsequent Corner Restoration

Year surveyed 11-2-1987 By T. FREEMAN L. OLSON
Location filed _____
Monument END 1" PINE IN E-W RD DOWN
.25'

Evidence of Subsequent Corner Restoration

Year of search 2-5-1990 By W. CURD #11395
1987 FD 1" I.P. & TIES

CERT OF LOCATION DOC. No. 318320

Bearing Trees, Reference Objects

Species	Bearing	Trees	Reference Objects
<u>J. PINE</u>	<u>W. PINE</u>	<u>W. PINE</u>	
Diameter <u>6"</u>	<u>6"</u>	<u>6"</u>	
Bearing <u>N19W</u>	<u>S20W</u>	<u>S63W</u>	
Distance <u>77.85</u>	<u>46.94</u>	<u>50.15</u>	

Bearing Trees, Reference Objects

Subsequent Corner Restoration

Year surveyed 5/24/2002 By R. MUSTONEN #11946
Location filed _____
Monument FOUND CHARR'D REMAINS OF
SQUARED WOOD POST & PINE STUMP
REMAINS. SET 1 1/2" O.D. IRON PIPE 1.5'
NORTH OF E TWP. RD. & MARK FOLLOWING

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
JUL 1997 L. SCHELLACK
CERT OF SVY SHOWS MON FOUND

<u>CALK SPIKE</u>	<u>12" JACK PINE</u>	<u>N15°W</u>	<u>68.45</u>
<u>DLX NAIL</u>	<u>9" J.P.</u>	<u>N20°E</u>	<u>81.30</u>
<u>DLX NAIL</u>	<u>15" WHITE PINE</u>	<u>S20°W</u>	<u>31.65</u>

DETERMINED MONUMENT SET BY W. CURD
& CERTIFIED IN 1990 WAS SET INCORRECT
AT REVERSED PROPORTION

Mar 2003 A. Mustonen #11946
Cert. of Sv. shows Mon. Found

Oct. 1999 T. Miller #23046
Cert. of Sv. shows mon. found

Remonumentation certificate prepared _____

By _____

Filed at _____

Date _____