



T. 140 R. 31 M. 5TH Coordinates: X _____ Y _____
NE 25? Corner common to sections 24, 25 AND 19, 30-140-30
 MC#1

EXISTING SURVEYS

Original Government Survey

Year surveyed 1865
 Original monument Post

Bearing Trees

Species	<u>N. PINE</u>	<u>N. PINE</u>	_____
Diameter	<u>9"</u>	<u>12"</u>	_____
Bearing	<u>S65E</u>	<u>S52W</u>	_____
Distance	<u>177 LKS</u>	<u>200 LKS</u>	_____

Original Evidence Found

Year of search _____ By _____
 Monument found _____

Original Bearing Trees Found

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

O = Corner

Subsequent Corner Restoration

Year surveyed 1913 By JOHN CURO
 Location filed COUNTY SURVEY RECORD BOOK B" P. 29
 Monument FIND CORNER BY CURO & STUMPS OF OLD GOVT B.T.S.
9" N. PINE S65E 177 LKS, 12" N. PINE S52W 200 LKS
SET 2 1/2 x 48" GALV. I.P. W/CAP
BOOK E" P. 437 - IRON MONUMENT

Bearing Trees, Reference Objects

Species	<u>N. PINE</u>	<u>N. PINE</u>	_____
Diameter	<u>10"</u>	<u>10"</u>	_____
Bearing	<u>S37.30E</u>	<u>S30W</u>	_____
Distance	<u>62.70'</u>	<u>78.90'</u>	_____

1913 TIES.

Evidence of Subsequent Corner Restoration

Year of search 1914 By DONNER
COUNTY BOOK "D" P. 48 FIND IRON CORNER.

1975 - Co Hwy Dept - Co Rd # 40
USGLO Corner in place

Bearing Trees, Reference Objects

_____	_____	_____
_____	_____	_____
_____	_____	_____

R-25

Subsequent Corner Restoration

Year surveyed _____ By _____
 Location filed _____
 Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
PLAT - PLAT OF SOUTH HACKENSACK
JOHN CURO 1906

PLAT - SOUTHBEACH ACRES
G. H. STEVENSON 1981

Certificate - Jim Nielson - Minn DOT - 1983

Find 1946 GLO Brass disc in one stump of 1913 B.T.

N: D 8" w. Pine S18W 118.52'

N: D 8" Maple S2W 65.88'

N: D 8" w. Oak S32E 59.19'

Blaze in 1913 N. Pine stump S37-30E 63.2'
Doc # 267917

July 1905, Twp rd order shows no survey

Remonumentation certificate prepared _____
 Filed at _____

By _____
 Date _____