


Index No. JR1

CASS COUNTY LAND CORNER RECORD

T. 141 R. 25 M. 5TH Coordinates: X _____ Y _____
NE 14 Corner common to sections 11, 12, 13, 14



O = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1871
Original monument POST

Original Evidence Found

Year of search _____ By _____
Monument found _____

	Bearing Trees			
Species	<u>ELM</u>	<u>BIRCH</u>	<u>CEDAR</u>	<u>BIRCH</u>
Diameter	<u>11"</u>	<u>8"</u>	<u>16"</u>	<u>7"</u>
Bearing	<u>S62E</u>	<u>S44W</u>	<u>N37 1/2 W</u>	<u>N20E</u>
Distance	<u>31 LKS</u>	<u>12 LKS</u>	<u>20 LKS</u>	<u>53 LKS</u>

Original Bearing Trees Found

Species	_____	_____	_____	_____
Diameter	_____	_____	_____	_____
Bearing	_____	_____	_____	_____
Distance	_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

Bearing Trees, Reference Objects

Species	_____	_____	_____	_____
Diameter	_____	_____	_____	_____
Bearing	_____	_____	_____	_____
Distance	_____	_____	_____	_____

Bearing Trees, Reference Objects

Species	_____	_____	_____	_____
Diameter	_____	_____	_____	_____
Bearing	_____	_____	_____	_____
Distance	_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Remonumentation certificate prepared _____
Filed at _____

By _____
Date _____