


Index No. N 19

CASS COUNTY LAND CORNER RECORD

T. 141 R. 25 M. 5TH Coordinates: X _____ Y _____
N 14, 23 Corner common to sections 14, 23



EXISTING SURVEYS

Original Government Survey

Year surveyed 1871
Original monument POST

Original Evidence Found

Year of search _____ By _____
Monument found _____

Bearing Trees	
Species <u>CEDAR</u>	<u>FIR</u>
Diameter <u>8"</u>	<u>7"</u>
Bearing <u>N 15E</u>	<u>S 46W</u>
Distance <u>13 LKS</u>	<u>12 LKS</u>

Original Bearing Trees Found

Species _____	_____	_____	_____
Diameter _____	_____	_____	_____
Bearing _____	_____	_____	_____
Distance _____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1917 By J.H. FLYNN
Location filed COUNTY BOOK "C" P. 35
Monument POST AND OLD GALT BITS: 10" CEDAR N 15E
13 LKS, 7" FIR S 46W 12 LKS, LARGE BOULDER - WEST
END 13.2' SOUTH

Evidence of Subsequent Corner Restoration

Year of search 1985 By USFS
Corner Certificate - Doc # 285573
Find large boulder - only one in area
set 2 1/2 x 60" 1 1/2" w/ 3" brass cap from
boulder.

Bearing Trees, Reference Objects

Species _____	_____	_____	_____
Diameter _____	_____	_____	_____
Bearing _____	_____	_____	_____
Distance _____	_____	_____	_____

Bearing Trees, Reference Objects

<u>Sugar Maple</u>	<u>W. Birch</u>	<u>Boulder NW End</u>	<u>Metal/lat</u>
<u>7.1"</u>	<u>8.2"</u>	<u>5.5' x 2.5'</u>	<u>8' long</u>
<u>N 8 W</u>	<u>S 75 E</u>	<u>South</u>	<u>E & S</u>
<u>35.54'</u>	<u>60.85'</u>	<u>13.2'</u>	<u>3'</u>

N-19

Subsequent Corner Restoration

Year surveyed 12/04 By CCSO
Location filed 2002.047
Monument Found USFS Brass cap, up
1.8' steel posts and Boulder good.
8" Ash N 45° W, 46.67' db1 hd no. 1

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
Certificate - Ken Whitehorn - USFS - 1985

Remonumentation certificate prepared _____ By _____
Filed at _____ Date _____