


Index No. V 13

CASS COUNTY LAND CORNER RECORD

T. 141 R. 25 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
NE 33 Corner common to sections 27, 28, 33, 34



EXISTING SURVEYS

**Original Government Survey**  
 Year surveyed 1871  
 Original monument POST

**Bearing Trees**

Species	<u>MARCE</u>	<u>MARCE</u>	<u>ASH</u>	<u>LINDEN</u>
Diameter	<u>6"</u>	<u>6"</u>	<u>7"</u>	<u>7"</u>
Bearing	<u>N75W</u>	<u>N18E</u>	<u>S45W</u>	<u>S54E</u>
Distance	<u>4 LKS</u>	<u>43 LKS</u>	<u>57 LKS</u>	<u>35 LKS</u>

**Original Evidence Found**  
 Year of search \_\_\_\_\_ By \_\_\_\_\_  
 Monument found \_\_\_\_\_

**Original Bearing Trees Found**

Species	_____	_____	_____	_____
Diameter	_____	_____	_____	_____
Bearing	_____	_____	_____	_____
Distance	_____	_____	_____	_____

O = Corner

**Subsequent Corner Restoration**  
 Year surveyed 1913 By J. H. FLYNN  
 Location filed COUNTY BOOK "C" P. 39-40  
 Monument FIND ALL OLD GOVT. B.T.S.

**Evidence of Subsequent Corner Restoration**  
 Year of search \_\_\_\_\_ By \_\_\_\_\_

**Bearing Trees, Reference Objects**

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

**Bearing Trees, Reference Objects**

_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

**Subsequent Corner Restoration**  
 Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
 Location filed \_\_\_\_\_  
 Monument \_\_\_\_\_

**Evidence of Subsequent Corner Restoration Found**  
 Year of search \_\_\_\_\_ By \_\_\_\_\_

Remonumentation certificate prepared \_\_\_\_\_ By \_\_\_\_\_  
 Filed at \_\_\_\_\_ Date \_\_\_\_\_