


Index No. V 17

CASS COUNTY LAND CORNER RECORD

T. 141 R. 25 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
NE 34 Corner common to sections 26, 27, 34, 35



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1871  
Original monument POST

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

Bearing Trees

Species	Bearing	Tree	Distance
<u>SPRUCE</u>	<u>SRE</u>	<u>ASPEN</u>	<u>WILLOW</u>
<u>9"</u>	<u>10"</u>	<u>8"</u>	<u>5"</u>
<u>N44E</u>	<u>SRE</u>	<u>S40W</u>	<u>N74W</u>
<u>36 LKS</u>	<u>58 LKS</u>	<u>65 LKS</u>	<u>12 LKS</u>

Original Bearing Trees Found

Species	Bearing	Distance
_____	_____	_____
_____	_____	_____
_____	_____	_____

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration

Year of search \_\_\_\_\_ By \_\_\_\_\_

Bearing Trees, Reference Objects

Species	Bearing	Distance
_____	_____	_____
_____	_____	_____
_____	_____	_____

Bearing Trees, Reference Objects

Species	Bearing	Distance
_____	_____	_____
_____	_____	_____
_____	_____	_____

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_

Remonumentation certificate prepared \_\_\_\_\_ By \_\_\_\_\_  
Filed at \_\_\_\_\_ Date \_\_\_\_\_